

UPRN B76A4 General Needs Flatted Accommodation Fire Risk Assessment (FRA)

Regulatory Reform (Fire Safety) Order 2005

	Next review due on:	6-Aug-19 6-Aug-18				
	Date of FRA:					
	Responsible person (e.g. housing provider): Chief Executive, Barnet Homes (e.g. housing provider)					
287-306	Fire Risk Assessor (include relevant professional memberships and/or qualifications)	(include relevant professionalnecessary qualifications, competency and experience in Fire Risk Management that give him the status of "Competent Person" as described in articles 15 and 18 of the 'Regulatory Reform (Fire Safety) Order 2005', for properties in England &				
Address of premises: 1-60 Harpenmead Point NW2 2LL	Person managing fire safety for the premises: Health & Safety Manager					
	Did you consult with any other i	Did you consult with any other individual during the FRA? No				
	If yes, provide Name					
	Position	within company				
Barnet Homes UPRN: B76A4	Recommended review date:	The person managing fire safety should monitor the progress of work undertaken in rectifying the deficiencies reported and should ensure that checks are undertaken at target completion dates. A follow up inspection (taking the form of an interim fire risk assessment review) should be undertaken no more than one month from the time when the reported 'Priority A' deficiencies have been identified and additionally in six months by which time Priority B deficiencies should have been actioned. It is Barnet Homes policy that a review of the fire risk assessment will be undertaken no later than 12 months from the date of inspection.				