

Effective: 01/03/2021 to 08/07/2022

Asset Number: 1021.00 to 1021.00

Display Action Officer: No

Site: FRIERN BARNET LANE (20016720)

Site: FRIERN BARNET LANE (20016720)

Locality: FRIERN BARNET, LONDON, BARNET

Area: North

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,021.00	Asset - Locn.:	B550_/00320 - FRIERN BARNET LANE - FRIERN BARNET L	Feature Type:	HW: Network Section		Area:	North
Batch:	91019563 - Inspection Batch		Route:	Area 3 WK10			Date:	20/06/2022
31014378	Dislodged kerb stone Relay 1 LM kerb stone Replace 2LM concrete situ with granite kerb stone	20/06/2022	257 Friern Barnet Lane, London, N20 OND	*HW: Kerb Issue Granite Reset	Internal		Committed	41017952
31014379	Cracked slab and uneven blocks Replace x1 750 slab Lift and relay 1m2 red blocks	20/06/2022	267 Friern Barnet Lane, London, N20 OND	*HW: Footway Issue Slab	Internal		Committed	41017951
Batch:	91018020 - Inspection Batch		Route:	Ad Hoc Route			Date:	06/05/2022
31013217	Footway damaged caused by vehicles. Replace 10m2 slabs with bitmac	06/05/2022	259- 261 Friern Barnet Lane, London, N20 OND	*HW: Footway Issue Bitmac	Internal		Committed	41016378
Batch:	91015156 - Inspection Batch		Route:	Area 3 WK46			Date:	09/03/2022
31010918	LFL Renew 1x600mm paving slab. Renew 1m2 of bitmac to remove trip hazard	09/03/2022	275 Friern Barnet Lane, London, N20 OND	*HW: Footway Issue Slab	Internal		Committed	41013516
Batch:	91014132 - Inspection Batch		Route:	Ad Hoc Route			Date:	16/02/2022
31009988	Reset 1LM of dislodged Granite kerb.	16/02/2022	47 Rasper Road, London, N20 0LU	*HW: Kerb Issue Granite Reset	Internal		Committed	41012115
Batch:	91014131 - Inspection Batch		Route:	Ad Hoc Route			Date:	16/02/2022
31009987	Reset 1LM of dislodged Granite kerb. Raised as Cat1 as kerbstone is in carriageway.	16/02/2022	266 Friern Barnet Lane, London, N20 ONH	*HW: Kerb Issue Granite Reset	Internal		Committed	41012114
Batch:	91011663 - Inspection Batch		Route:	Area 3 WK34			Date:	16/12/2021
31008266	LFL Breakout damaged bitmac and renew 1m2	16/12/2021	Jewellers Apartments, 272 Friern Barnet Lane, London, N20 0NH	*HW: Footway Issue Bitmac	Internal		Committed	41009692
Batch:	91011577 - Inspection Batch		Route:	Ad Hoc Route			Date:	14/12/2021
31008191	Relay sunken paving slabs 2m2 renew bitmac 1m2	14/12/2021	Rear of 45 Rasper Road, London, N20 0LU	*HW: Footway Issue Slab	Internal		Committed	41009613
Batch:	91011576 - Inspection Batch		Route:	Ad Hoc Route			Date:	14/12/2021
31008190	Footway sunken place safety barriers around defect	14/12/2021	Rear of 45 Rasper Road, London, N20 0LU	*HW: Footway Issue Slab	Internal		Committed	41009612
Batch:	91007713 - Inspection Batch		Route:	Ad Hoc Route			Date:	30/09/2021
31006092	Replace all marked paving slabs with bitmac 3m2 as vehicles illegally crossing footway to gain access to drive. So no point relaying slabs at this time	30/09/2021		*HW: Footway Issue Slab	Internal		Committed	41006898
Batch:	91006805 - Inspection Batch		Route:	Area 3 WK22			Date:	07/09/2021
	No actionable defects found							

Effective: 01/03/2021 to 08/07/2022

Asset Number: 1021.00 to 1021.00

Display Action Officer: No

Site: FRIERN BARNET LANE (20016720)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,021.00	Asset - Locn.:	B550__/00320 - FRIERN BARNET LANE - FRIERN BARNET L	Feature Type:	HW: Network Section		Area: North	
Batch:	91003133 - Inspection Batch			Route:	Area 3 WK10			Date: 09/06/2021
31002755	Take and relay 5m2 of paving slabs which are rocking. There are schools located on this street.	09/06/2021	Between 269 & 267 Friern Barnet Lane, *HW: Footway Issue Slab London, N20 0ND		Internal		Committed	41002826
Batch:	91002564 - Inspection Batch			Route:	Ad Hoc Route			Date: 20/05/2021
31002198	Breakout and renew concrete where old drain cover was. 1m2 may require type to fill small void before completing concrete (Enquiry 11002347)	20/05/2021	Outside 275 FRIERN BARNET LANE LONDON BARNET N20 0ND	*HW: Footway Issue Concrete	Internal		Committed	41002225