

UPRN B76A5

General needs flatted accommodation Fire Risk Assessment (FRA)

Regulatory Reform (Fire Safety) Order 2005

	Next review due on *:	6-Aug-19 6-Aug-18		
	Date of FRA:			
	Responsible person (e.g. housi	ng provider):	Chief Ex	cecutive, Barnet Homes
808	Fire Risk Assessor (include relevant professional memberships and/or qualifications)	The Fire Risk Assessment was undertaken by Mr H McLean who has the necessary qualifications, competency and experience in Fire Risk Management that give him the status of "Competent Person" as described in articles 15 and 18 of the 'Regulatory Reform (Fire Safety) Order 2005', for properties in England & Wales, and the 'Fire Safety (Scotland) Regulations 2006' for those in Scotland. This legislation now supersedes all previous fire legislation for England, Wales & Scotland and forms the 'Fire Regulations'. He is an ex-fire enforcement officer by profession; has been trained through the Fire Service College in all necessary disciplines of fire safety, building design and building behaviour under fire conditions and is considered to be sufficiently practised in the necessary skills to enable him to carry out a practical fire risk assessment.		
Address of premises:	Person managing fire safety for	r the premises:	Health 8	k Safety Manager
Templewood Point 1-60 NW2 2AX (Did you consult with any other i If yes, provide Name Position	ndividual during the within company	e FRA?	No
Barnet Homes UPRN: B76A5	Recommended review date:	The person mana	deficiencies r	fety should monitor the progress of work undertaken reported and should ensure that checks are ion dates.
* The next review may not necessarily be a physical s desktop review. This is dependent on whether or not out since the last FRA, any reported changes or activ well as the building's level of fire risk	works have been carried	should be undert 'Priority P0' defic which time Priorit It is Barnet Hom	taken no mo iencies have ty P1 deficie ies policy tha	the form of an interim fire risk assessment review) re than one month from the time when the reported been identified and additionally in six months by ncies should have been actioned. at a review of the fire risk assessment will be months from the date of inspection.