

CLAIMANT - [REDACTED]

REFERENCE - [REDACTED]

LONDON BOROUGH OF BARNET - HIGHWAYS ACCIDENT REPORT DOCUMENT

DATE OF ACCIDENT/INCIDENT 18 September 2019

LOCATION Friern Park, just before junction with Northwood Gardens N12

INSPECTION

Inspecting Officer (Print Name) [REDACTED] Date of Inspection 24-10-19

Is the Accident Location the responsibility of the London Borough of Barnet? Yes ☒ No ☐

If No state name of the responsible Authority

Category of Road lesser urban Ward Woodhouse

Scheduled Frequency of Inspections Yearly

Description of condition of Carriageway/Pavement Surface Traffic Island with
Kerb edge block Paved Footway with Plastic board
Knocked out of socket.Defect Identified? Yes ☒ No ☐

If Yes state: Height of Trip (Paving) ?

Maximum Depth (Pothole) ?

Number of Photographs taken and attached 4

(NB - Ensure that a measuring board is used when taking photographs.)

Is there evidence of any repairs? If so give details NO

Repair Instigated as a Direct Result of Inspection? Yes ☒ No ☐

If Yes state: Date Requisitioned 25-10-19 (Attach Copy Order)

Works Order/LA Number Category C2

Name of Contractor D.L.O

Completion Period Date Completed

CAUSE OF DAMAGE

Wear & Tear	☐	Vehicle Damage	☒	Tree Roots	☐	Stat Company/Contractor	☐	Other	☐
-------------	--------------------------	----------------	-------------------------------------	------------	--------------------------	-------------------------	--------------------------	-------	--------------------------

If other please give details

CLAIMANT - [REDACTED]

REFERENCE- [REDACTED]

For damage caused by Stat Company or Contractor, please provide:

R.A.S.W.A Notice/ Works Order LA Number	Start Date of Works	End Date of Works

INSPECTION REGIME

Please provide details of all Cyclic Inspections for the 12 months prior to the date of accident and the one following:

Inspection date	4-12-18	18-9-19		
Defects recorded on Inspection at Location	/	/		
Repair Orders Raised including date and LA order number)				
Repair carried out (including date, LA order number, and contractor)				

OTHER WORKS

Any Works carried out between the Accident Date and Date of Your Inspection?

Yes ☐ No ☐

If Yes state: Reason for works

LA Order/QG Number

Date Order Raised Date Order Completed

SIGNATURE [REDACTED]

DATE 24-10-19

CTIONS ONLY (CYC) Note : If no Date Loaded then the Inspection did not come from the Mobile Date Inspected From : '01-SEP-2018', Date Inspected To : '18-OCT-2019', Road Name : %FRIERN PARK - FRIERN PARK FROM GLE

Inspection id	Date inspected	Date loaded	Road id	Road name	Number of defects SUM	Inspector	Initiation type
116104	18-Sep-2019	18-Sep-2019	5090U16800/000000	FRIERN PARK - FRIERN PARK FROM GLEN HURST ROAD TO GROVE ROAD	1		INSP - CYC (Area 1 Wk 23)
103534	04-Dec-2018	04-Dec-2018	5090U16800/000000	FRIERN PARK - FRIERN PARK FROM GLEN HURST ROAD TO GROVE ROAD	0		INSP - CYC (Area 1 Wk 34)

[illegible]



24/10/2019

24/10/2019

REF NO [REDACTED]
INSP. DATE 24-10-19
LOC Friern Park N12
By Northwood gndy
INS. OFFICER [REDACTED]
MEASURE 1 2 3 4 5 6 7 8 9
PHOTO No 1 2 3 4 5 6 7 8 9
GM MKII SEP 18mm 5 0 5
USE DRY MARKER ONLY
BARNET LONDON BOROUGH

24/10/2019



100mm

REF NO	24-10-19
NSP. DATE	Frern Park N12
LOC	By Northwood gully
MEASURE	INSPI OFFICER ANT
PHOTO No	1 2 3 4 5 6 7 8 9

BARNET
LONDON BOROUGH

USE DRY MARKER ONLY



24/10/2019

REF NO
INSP. DATE
LOC
MEASURE
PHOTO No

24-10-19
Friern Park N12
By Northwood Gate

INSPECTOR
MM OFFICER
ANT

1 2 3 4 5 6 7 8 9

USE DRY MARKER ONLY

BARNET
LONDON BOROUGH

18mm
15
10
5

GM MKU
SEP