

Nodes

No on map	Ward	Road	Type	Num pipes	Usage	Cover Level	Last Inspection	External Id	Unique Id
1	Garden Suburb	LYTTELTON ROAD	Gully / Standard	0	Surface		31-10-2020	BAR2-130	930012686
GENERAL OBSERVATIONS COVER_MATERIAL Iron ; COVER_SHAPE Rectangle ; COVER DUTY HeavyDuty ; CYCLE BiennialYear1 ; ACCESS OK ; OPERATIONAL ON ARRIVAL not obstructed ; OPERATIONAL ON LEAVING Unknown ; COVER_CONDITION OK ; CLEANED Yes ; SILT_LEVEL 50% ; INSPECTION COMMENT Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable ; JETTING COMPLETED No ; USER NAME Historic data import						OPERATIONS CARRIED OUT Clean			
2	Garden Suburb	LYTTELTON ROAD	Gully / Standard	0	Surface		31-10-2020	BAR2-131	930012696
GENERAL OBSERVATIONS COVER_MATERIAL Iron ; COVER_SHAPE Rectangle ; COVER DUTY HeavyDuty ; CYCLE BiennialYear1 ; ACCESS OK ; OPERATIONAL ON ARRIVAL not obstructed ; OPERATIONAL ON LEAVING Unknown ; COVER_CONDITION OK ; CLEANED Yes ; SILT_LEVEL 100% ; SILT DEFECT RequiredDigOut ; INSPECTION COMMENT Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable ; JETTING COMPLETED No ; USER NAME Historic data import						OPERATIONS CARRIED OUT Clean			
3	Garden Suburb	LYTTELTON ROAD	Gully / Standard	0	Surface		31-10-2020	BAR2-143	930012810
GENERAL OBSERVATIONS COVER_MATERIAL Iron ; COVER_SHAPE Rectangle ; COVER DUTY HeavyDuty ; CYCLE BiennialYear1 ; ACCESS OK ; OPERATIONAL ON ARRIVAL not obstructed ; OPERATIONAL ON LEAVING Unknown ; COVER_CONDITION OK ; CLEANED Yes ; SILT_LEVEL 50% ; INSPECTION COMMENT Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable ; JETTING COMPLETED No ; USER NAME Historic data import						OPERATIONS CARRIED OUT Clean			
4	Garden Suburb	LYTTELTON ROAD	Gully / Standard	0	Surface		31-10-2020	BAR2-132	930012706
GENERAL OBSERVATIONS COVER_MATERIAL Iron ; COVER_SHAPE Rectangle ; COVER DUTY HeavyDuty ; CYCLE BiennialYear1 ; ACCESS OK ; OPERATIONAL ON ARRIVAL not obstructed ; OPERATIONAL ON LEAVING Unknown ; COVER_CONDITION OK ; CLEANED Yes ; SILT_LEVEL 50% ; INSPECTION COMMENT Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable ; JETTING COMPLETED No ; USER NAME Historic data import						OPERATIONS CARRIED OUT Clean			
5	Garden Suburb	LYTTELTON ROAD	Gully / Standard	0	Surface		31-10-2020	BAR2-144	930012819
GENERAL OBSERVATIONS COVER_MATERIAL Iron ; COVER_SHAPE Rectangle ; COVER DUTY HeavyDuty ; CYCLE BiennialYear1 ; ACCESS OK ; OPERATIONAL ON ARRIVAL not obstructed ; OPERATIONAL ON LEAVING Unknown ; COVER_CONDITION OK ; CLEANED Yes ; SILT_LEVEL 60% ; INSPECTION COMMENT Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable ; JETTING COMPLETED No ; USER NAME Historic data import						OPERATIONS CARRIED OUT Clean			
6	Garden Suburb	LYTTELTON ROAD	Gully / Standard	0	Surface		31-10-2020	BAR2-145	930012829
GENERAL OBSERVATIONS COVER_MATERIAL Iron ; COVER_SHAPE Rectangle ; COVER DUTY HeavyDuty ; CYCLE BiennialYear1 ; ACCESS OK ; OPERATIONAL ON ARRIVAL not obstructed ; OPERATIONAL ON LEAVING Unknown ; COVER_CONDITION OK ; CLEANED Yes ; SILT_LEVEL 100% ; INSPECTION COMMENT Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable ; JETTING COMPLETED No ; USER NAME Historic data import						OPERATIONS CARRIED OUT Clean			
7	Garden Suburb	LYTTELTON ROAD	Gully / Standard	0	Surface		31-10-2020	BAR2-146	930012839
GENERAL OBSERVATIONS COVER_MATERIAL Iron ; COVER_SHAPE Rectangle ; COVER DUTY HeavyDuty ; CYCLE BiennialYear1 ; ACCESS OK ; OPERATIONAL ON ARRIVAL not obstructed ; OPERATIONAL ON LEAVING Unknown ; COVER_CONDITION OK ; CLEANED Yes ; SILT_LEVEL 60% ; INSPECTION COMMENT Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable ; JETTING COMPLETED No ; USER NAME Historic data import						OPERATIONS CARRIED OUT Clean			
8	Garden Suburb	LYTTELTON ROAD	Gully / Standard	0	Surface		31-10-2020	BAR2-147	930012850
GENERAL OBSERVATIONS COVER_MATERIAL Iron ; COVER_SHAPE Rectangle ; COVER DUTY HeavyDuty ; CYCLE BiennialYear1 ; ACCESS OK ; OPERATIONAL ON ARRIVAL not obstructed ; OPERATIONAL ON LEAVING Unknown ; COVER_CONDITION OK ; CLEANED Yes ; SILT_LEVEL 60% ; INSPECTION COMMENT Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable ; JETTING COMPLETED No ; USER NAME Historic data import						OPERATIONS CARRIED OUT Clean			

Channels

No on map	Ward	Road	Type	Diameter	Material	Length	Last Inspection	External Id	Unique Id
-----------	------	------	------	----------	----------	--------	-----------------	-------------	-----------

Overview Map

