

## Nodes

No on map	Ward	Road	Type	Num pipes	Usage	Cover Level	Last Inspection	External Id	Unique Id
1	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3822	930016096
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
2	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3805	930016079
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
3	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3764	930016038
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
4	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3743	930016015
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
5	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3693	930015960
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
6	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3684	930015950
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
7	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3626	930015888
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
8	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3625	930015887
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
9	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3529	930015786
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			

No on map	Ward	Road	Type	Num pipes	Usage	Cover Level	Last Inspection	External Id	Unique Id
10	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3528	930015785
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
11	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3404	930015652
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
12	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3405	930015653
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
13	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		27-10-2020	BAR3355	930015599
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>BrokenLid</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:39 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
14	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR3273	930015513
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
15	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR3249	930015487
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
16	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		01-06-2020	BARA39043	930024514
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:Parked Car Revisit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
17	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BARA38828	930024478
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
18	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR3069	930015277
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
19	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR3061	930015269

No on map	Ward	Road	Type	Num pipes	Usage	Cover Level	Last Inspection	External Id	Unique Id
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
20	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2959	930015156
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
21	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2958	930015155
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
22	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2867	930015057
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
23	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2861	930015051
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
24	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2744	930014924
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
25	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2741	930014921
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
26	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2617	930014788
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
27	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2616	930014787
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
28	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2611	930014782

No on map	Ward	Road	Type	Num pipes	Usage	Cover Level	Last Inspection	External Id	Unique Id
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>90%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
29	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2612	930014783
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>90%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
30	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2564	930014725
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
31	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2556	930014716
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>60%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
32	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2406	930014574
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
33	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2401	930014570
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>50%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
34	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2313	930014470
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
35	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2307	930014413
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
36	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2160	930012977
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>90%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
37	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2159	930012965



No on map	Ward	Road	Type	Num pipes	Usage	Cover Level	Last Inspection	External Id	Unique Id
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>90%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
38	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2154	930012920
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
39	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2153	930012909
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>60%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
40	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR2072	930012160
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>40%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
41	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		01-06-2020	BAR2060	930012051
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>90%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:Parked Car Revisit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
42	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-01-2021	BAR1950	930010889
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>60%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:3rd Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
43	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1936	930010735
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
44	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-01-2021	BAR1908	930010434
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:3rd Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
45	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1836	930009686
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>50%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
46	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BARA38977	930024507

No on map	Ward	Road	Type	Num pipes	Usage	Cover Level	Last Inspection	External Id	Unique Id
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
47	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1719	930008435
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
48	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1714	930008381
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
49	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-01-2021	BAR1603	930007209
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:3rd Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
50	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1602	930007198
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
51	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1563	930006799
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
52	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1478	930005832
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>90%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
53	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1476	930005808
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>90%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
54	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-01-2021	BAR1470	930005734
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>60%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:3rd Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
55	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-01-2021	BAR1471	930005746

No on map	Ward	Road	Type	Num pipes	Usage	Cover Level	Last Inspection	External Id	Unique Id
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>60%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:3rd Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
56	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		01-06-2020	BAR1421	930004997
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:Parked Car Revisit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
57	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1419	930004954
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>100%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
58	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BARA39005	930024513
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>50%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
59	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BARA38989	930024508
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
60	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1290	930003380
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>60%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
61	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BARA38991	930024509
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
62	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1177	930002054
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
63	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1174	930002016
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>50%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
64	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1173	930002004

No on map	Ward	Road	Type	Num pipes	Usage	Cover Level	Last Inspection	External Id	Unique Id
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>40%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
65	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BARA38999	930024512
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>60%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
66	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-05-2020	BAR1175	930002028
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>80%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:1st Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			
67	Garden Suburb	THE BISHOPS AVENUE	Gully / Standard	0	Surface		29-01-2021	BARA38997	930024511
	GENERAL OBSERVATIONS COVER_MATERIAL <b>Iron</b> ; COVER_SHAPE <b>Rectangle</b> ; COVER DUTY <b>HeavyDuty</b> ; CYCLE <b>BiennialYear1</b> ; ACCESS <b>OK</b> ; OPERATIONAL ON ARRIVAL <b>not_obstructed</b> ; OPERATIONAL ON LEAVING <b>Unknown</b> ; COVER_CONDITION <b>OK</b> ; CLEANED <b>Yes</b> ; SILT_LEVEL <b>70%</b> ; INSPECTION COMMENT <b>Barnet inspection data imported June 2021. Visit:3rd Visit Cell_no:42 Vulnerable:Not Vulnerable</b> ; JETTING COMPLETED <b>No</b> ; USER NAME <b>Historic data import</b>					OPERATIONS CARRIED OUT Clean			