

Effective: 01/07/2022 to 13/01/2023

Asset Number: 1002.00 to 1002.00

Display Action Officer: No

Site: LONGLAND DRIVE (20027300)

Site: LONGLAND DRIVE (20027300)

Locality: WHETSTONE, LONDON, BARNET

Area: North

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,002.00	Asset - Locn.: U27300/00002 - LONGLAND DRIVE - GREENWAY TO LAURE			Feature Type: HW: Network Section			Area: North	
Batch: 91029080 - Inspection Batch				Route: Ad Hoc Route				Date: 10/01/2023
31019971	Plug repair 4m2 c/w pothole	10/01/2023	112 Longland Drive, Totteridge, N20 8HL, England, United Kingdom	*HW: Pothole Patch <10m2	Internal		Committed	41025347
Batch: 91028124 - Inspection Batch				Route: Ad Hoc Route				Date: 21/12/2022
31019285	Break out and relay 8m2 c/w.	21/12/2022	112 Longland Drive, Totteridge, N20 8HL, England, United Kingdom	*HW: Pothole Patch <10m2	Internal		Committed	41024600
Batch: 91025898 - Inspection Batch				Route: Ad Hoc Route				Date: 02/11/2022
31017893	Break out and relay 1m2 c/w pothole	02/11/2022	42 Longland Drive, Totteridge, N20 8HJ, England, United Kingdom	*HW: Pothole Patch <10m2	Internal		Committed	41022791
Batch: 91025897 - Inspection Batch				Route: Ad Hoc Route				Date: 02/11/2022
31017892	Break out and relay 2m2 c/w pothole.	02/11/2022	50 Longland Drive, Totteridge, N20 8HJ, England, United Kingdom	*HW: Pothole Patch <10m2	Internal		Committed	41022790
Batch: 91021867 - Inspection Batch				Route: Beat 3 WK20 - (Area 3 - 6Insp)				Date: 15/08/2022
31015673	Break out and relay 1m2 c/w pothole	15/08/2022	91 Longland Drive, London, N20 8HN	*HW: Pothole Patch <10m2	Internal		Committed	41019822

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,002.00	Asset - Locn.: U27300/00002 - LONGLAND DRIVE - GREENWAY TO LAURE			Feature Type: HW: Network Section		Area: North	
41004104	Damaged Manhole Cover - Damaged water board man hole cover Category: Pavement Damaged/Cracked Damage manhole cover broken outside 49 longland driver, lodon n20 8hh Requires urgent attention as is a trip hazard Location: Easting/Northing: 525970/193689 (51.627927, -0.181487) Nearest road to the pin placed on the map (automatically generated by Bing Maps): 45 Longland Drive, London, N20 8HH Nearest postcode to the pin placed on the map (automatically generated): N20 8HH (139m away) (Enquiry 11005190) (HW: Manhole Cover Issue)	outside 49 longland driver, lodon n20 8hh	CAT2: 7 day	Job Queried	19/07/2021	09/08/2021	Est. TKJVPL/200385

Effective: 01/07/2022 to 13/01/2023

Asset Number: 1002.00 to 1002.00

Display Action Officer: No

Site: LONGLAND DRIVE (20027300)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,002.00	Asset - Locn.: U27300/00002 - LONGLAND DRIVE - GREENWAY TO LAURE		Feature Type: HW: Network Section		Area: North	
41011686	refresh ALL road markings from Totteridge Lane to Northiam N20 (HW: Road Marking Issue)	Longland Dr from Totteridge Lane to Northiam N20	CAT4 - Contractor to Programme	Job Committed	10/02/2022	25/03/2022	Est. TKJVPL/201924
41014463	Carry out 71m2 patch repair to deteriorating carriageway. (*HW: Pothole Patch <10m2)	70 Longland Drive, London, N20 8HL	CAT2: 7 day	Job Cancelled	25/03/2022	12/04/2022	Est. TKJV/5110954
41017965	Footway Damaged by Builders - Single Storey Flat Green Roof Rear Extension, Single And Part Two Storey Side Extension, New Structural Openings, Replacement Stair To Access The Side Extension And Associated Internal Alterations (Enquiry 11015391) (*HW: Footway Issue Slab)	105 Longland Drive London N20 8HN	CAT3: 28 day	Job Completed on Site	21/06/2022	22/07/2022	Act. TKJVPL/202486
41019822	Break out and relay 1m2 c/w pothole (*HW: Pothole Patch <10m2)	91 Longland Drive, London, N20 8HN	CAT2: 7 day	Job Completed on Site	15/08/2022	24/08/2022	Act. TKJV/5114373
41022790	Break out and relay 2m2 c/w pothole. (*HW: Pothole Patch <10m2)	50 Longland Drive, Totteridge, N20 8HJ, England, United Kingdom	CAT1: 24 hour	Job Completed on Site	02/11/2022	04/11/2022	Act. TKJV/5116370
41022791	Break out and relay 1m2 c/w pothole (*HW: Pothole Patch <10m2)	42 Longland Drive, Totteridge, N20 8HJ, England, United Kingdom	CAT1: 24 hour	Job Completed on Site	02/11/2022	04/11/2022	Act. TKJV/5116371
41024600	Break out and relay 8m2 c/w. (*HW: Pothole Patch <10m2)	112 Longland Drive, Totteridge, N20 8HL, England, United Kingdom	CAT3: 28 day	Job Cancelled	21/12/2022	02/02/2023	Est. TKJV/5117607
41025347	Plug repair 4m2 c/w pothole (*HW: Pothole Patch <10m2)	112 Longland Drive, Totteridge, N20 8HL, England, United Kingdom	CAT1: 24 hour	Job Completed on Site	10/01/2023	13/01/2023	Act. TKJV/5118178