

Effective: 01/08/2022 to 19/02/2023

Asset Number: 1003.00 to 1003.00

Display Action Officer: Yes

Site: WATLING AVENUE (20044805)

Site: WATLING AVENUE (20044805)

Locality: BURNT OAK, EDGWARE, BARNET

Area: West

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,003.00	Asset - Locn.:	U44805/00000 - WATLING AVENUE FROM ORANGE HILL RO,	Feature Type:	HW: Network Section		Area: West	
Batch:	91030804 - Inspection Batch		Route:	Beat 4 WK41 - (Area 4 - 6Insp)	Officer:			Date: 02/02/2023
31021047	Reset 1lm granite kerb.	02/02/2023	13a Watling Avenue, Burnt Oak, HA8 0EL, England, United Kingdom. Nr lc26. Outside Oheneba foods.	*HW: Kerb Issue Granite Reset	Internal		Committed	41026608
31021045	Reset 3lm granite kerbs.	02/02/2023	91 Watling Avenue, Burnt Oak, HA8 0LT, England, United Kingdom. Outside Costcutter.	*HW: Kerb Issue Granite Reset	Internal		Committed	41026606
31021046	Rest 2lm granite kerbs.	02/02/2023	91 Watling Avenue, Burnt Oak, HA8 0LT, England, United Kingdom. Outside Cistcutter, by lc25.	*HW: Kerb Issue Granite Reset	Internal		Committed	41026607
Batch:	91030177 - Inspection Batch		Route:	Ad Hoc Route	Officer:			Date: 25/01/2023
31020648	Relay surface through and around trench, extend size of trench Trench located on the junction of the A5.	25/01/2023	112-114 Burnt Oak Broadway, Burnt Oak, HA8 0AD, England, United Kingdom	HW: Road Issue	Internal		Uncommitted	41026139
Batch:	91028945 - Inspection Batch		Route:	Ad Hoc Route	Officer:			Date: 06/01/2023
31019855	DO NOT COMMITE	06/01/2023	From 45-51 Watling Avenue, Burnt Oak, HA8 0LF, England, United Kingdom	HW: Footway Issue	Internal		Archived	41025224
Batch:	91028791 - Inspection Batch		Route:	Ad Hoc Route	Officer:			Date: 05/01/2023
31019768	DO NOT COMMIT Replace and rebuild damaged gully. Resurface carriageway around as marked 30m2	05/01/2023	3 Watling Avenue, Burnt Oak, HA8 0LQ, England, United Kingdom	*HW: Gully Issue surround	Internal		Committed	41025129
Batch:	91028767 - Inspection Batch		Route:	Beat 4 WK37 - (Area 4 - 6Insp)	Officer:			Date: 05/01/2023
31019754	Reset 3lm granite kerbs.	05/01/2023	42 Watling Avenue, Burnt Oak, HA8 0LT, England, United Kingdom	*HW: Kerb Issue Granite Reset	Internal		Committed	41025112
31019753	Make safe broken gully x1	05/01/2023	3 Watling Avenue, Burnt Oak, HA8 0LQ, England, United Kingdom	*HW: Gully Issue (Iron Works)	Internal		Committed	41025111
31019756	Repair 1m2 pothole. Unable to mark up due to traffic flow.	05/01/2023	91 Watling Avenue, Burnt Oak, HA8 0LT, England, United Kingdom	*HW: Pothole Patch <10m2	Internal		Committed	41025114
31019755	Replace 3x750, lift and relay 2m2 asp.	05/01/2023	80a Watling Avenue, Burnt Oak, HA8 0LU, England, United Kingdom	*HW: Footway Issue Slab	Internal		Committed	41025113
Batch:	91027274 - Inspection Batch		Route:	Beat 4 WK33 - (Area 4 - 6Insp)	Officer:			Date: 30/11/2022
31018734	Patch repair pothole 2m2	30/11/2022	2 Watling Avenue, at Pelican lights , junction Burnt Oak Broadway, Burnt Oak, HA8 0LL, England, United Kingdom	*HW: Pothole Patch <10m2	Internal		Committed	41023893
Batch:	91025843 - Inspection Batch		Route:	Beat 4 WK29 - (Area 4 - 6Insp)	Officer:			Date: 01/11/2022
31017865	Broken gully surround to replace x1 and reset surround 1m2	01/11/2022	3 Watling Avenue, Burnt Oak, HA8 0LQ, England, United Kingdom. Within bus stop "K".	*HW: Gully Issue (Iron Works)	Internal		Committed	41022754

Effective: 01/08/2022 to 19/02/2023

Asset Number: 1003.00 to 1003.00

Display Action Officer: Yes

Site: WATLING AVENUE (20044805)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,003.00	Asset - Locn.: U44805/00000 - WATLING AVENUE FROM ORANGE HILL RO,			Feature Type: HW: Network Section		Area: West	
Batch: 91024156 - Inspection Batch				Route: Beat 4 WK25 - (Area 4 - 6Insp)	Officer:		Date: 27/09/2022	
31016889	Reset displaced pavement inlet gully Grate x1.	27/09/2022	34 Watling Avenue, Burnt Oak, HA8 0LF, by pelican crossing	*HW: Gully Issue (Iron Works)	Internal		Committed	41021446
Batch: 91022854 - Inspection Batch				Route: Beat 4 WK21 - (Area 4 - 6Insp)	Officer:		Date: 31/08/2022	
No actionable defects found								
Batch: 91022362 - Inspection Batch				Route: Extras WK20 - Beat 4	Officer:		Date: 23/08/2022	
No actionable defects found								