

Effective: 01/01/2021 to 21/02/2024

Asset Number: 1003.00 to 1003.00

Display Action Officer: No

Site: HIGH STREET (20022440)

Site: HIGH STREET (20022440)

Locality: BARNET, BARNET

Area: North

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,003.00	Asset - Locn.: A1000_/00045 - HIGH STREET - HIGH STREET (A1000) FRO			Feature Type: HW	Network	Section	Area: North	
Batch: 91047943	- Inspection Batch			Route: Beat 3 WK41 - (Area 3 - 6Insp)				Date: 26/01/2024
	No actionable defects found							
Batch: 91046602	- Inspection Batch			Route: Beat 3 WK37 - (Area 3 - 6Insp)				Date: 03/01/2024
	No actionable defects found							
Batch: 91045441	- Inspection Batch			Route: Beat 3 WK33 - (Area 3 - 6Insp)				Date: 28/11/2023
	No actionable defects found							
Batch: 91044368	- Inspection Batch			Route: Ad Hoc Route				Date: 06/11/2023
31030510	Replace 2m2 slabs with bitmac by tree pit	06/11/2023	16 High Street, High Barnet, EN5 5RU, England, United Kingdom	*HW: Footway Issue Bitmac	Internal		Committed	41041939
Batch: 91043944	- Inspection Batch			Route: Beat 3 WK29 - (Area 3 - 6Insp)				Date: 25/10/2023
	No actionable defects found							
Batch: 91043088	- Inspection Batch			Route: Ad Hoc Route				Date: 09/10/2023
31029668	Break out and replace crushed bike rack.	09/10/2023	50 High Street, High Barnet, EN5 5SB, England, United Kingdom	*HW: Street Furn BollardReplac	Internal		Committed	41040842
Batch: 91042606	- Inspection Batch			Route: Beat 3 WK25 - (Area 3 - 6Insp)				Date: 26/09/2023
	No actionable defects found							
Batch: 91041339	- Inspection Batch			Route: Beat 3 WK21 - (Area 3 - 6Insp)				Date: 29/08/2023
	No actionable defects found							
Batch: 91039843	- Inspection Batch			Route: Beat 3 WK17 - (Area 3 - 6Insp)				Date: 25/07/2023
	No actionable defects found							
Batch: 91039558	- Inspection Batch			Route: Ad Hoc Route				Date: 19/07/2023
31027185	Break out and relay 3 l/m granite kerb.	19/07/2023	9a High Street, Underhill, EN5 5UE, England, United Kingdom. Junction with Normandy avenue.	*HW: Kerb Issue Granite Reset	Internal		Committed	41037618
Batch: 91038338	- Inspection Batch			Route: Beat 3 WK13 - (Area 3 - 6Insp)				Date: 27/06/2023
	No actionable defects found							
Batch: 91036825	- Inspection Batch			Route: Beat 3 WK09 - (Area 3 - 6Insp)				Date: 24/05/2023
31025488	Reset 1 l/m granite kerb.	24/05/2023	Barnet high St, Underhill, EN5 5SJ, England, United Kingdom. O/s paddy Power.	*HW: Kerb Issue Granite Reset	Internal		Committed	41035410
Batch: 91035227	- Inspection Batch			Route: Beat 3 WK05 - (Area 3 - 6Insp)				Date: 25/04/2023
	No actionable defects found							
Batch: 91033654	- Inspection Batch			Route: Beat 3 WK01 - (Area 3 - 6Insp)				Date: 29/03/2023
	No actionable defects found							
Batch: 91032187	- Inspection Batch			Route: Beat 3 WK45 - (Area 3 - 6Insp)				Date: 01/03/2023
31022077	Plug repair 1m2 c/w pothole.	01/03/2023	58 High Street, Underhill, EN5 5XY, England, United Kingdom	*HW: Pothole Patch <10m2	Internal		Committed	41027920

Effective: 01/01/2021 to 21/02/2024

Asset Number: 1003.00 to 1003.00

Display Action Officer: No

Site: HIGH STREET (20022440)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,003.00	Asset - Locn.:	A1000_/00045 - HIGH STREET - HIGH STREET (A1000) FRO	Feature Type:	HW	Network Section	Area:	North
Batch:	91030555 - Inspection Batch			Route:	Beat 3 WK41 - (Area 3 - 6Insp)			Date: 31/01/2023
31020865	Concrete fillet around box	31/01/2023	9a High Street, Underhill, EN5 5UE, England, United Kingdom. Corner of Normandy Avenue.	*HW: Footway Issue Mortar	Internal		Committed	41026406
Batch:	91028499 - Inspection Batch			Route:	Beat 3 WK37 - (Area 3 - 6Insp)			Date: 03/01/2023
	No actionable defects found							
Batch:	91027471 - Inspection Batch			Route:	Beat 3 WK33 - (Area 3 - 6Insp)			Date: 05/12/2022
	No actionable defects found							
Batch:	91025787 - Inspection Batch			Route:	Beat 3 WK29 - (Area 3 - 6Insp)			Date: 01/11/2022
31017829	Relay 1 l/m granite kerb	01/11/2022	99 High Street, Underhill, EN5 5RR, England, United Kingdom	*HW: Kerb Issue Granite Reset	Internal		Committed	41022716
31017827	Relay rocking slab.	01/11/2022	56b High Street, Underhill, EN5 5UR, England, United Kingdom	*HW: Footway Issue Slab	Internal		Committed	41022714
Batch:	91024082 - Inspection Batch			Route:	Beat 3 WK25 - (Area 3 - 6Insp)			Date: 26/09/2022
31016856	Break out and refillet around BT box	26/09/2022	10a High Street, Barnet, EN5 5RU	*HW: Footway Issue Mortar	Internal		Committed	41021395
31016855	Break out and refillet BT box	26/09/2022	9a High Street, Barnet, EN5 5UE. S/o lamp column 6	*HW: Footway Issue Mortar	Internal		Committed	41021394
Batch:	91022815 - Inspection Batch			Route:	Beat 3 WK21 - (Area 3 - 6Insp)			Date: 31/08/2022
	No actionable defects found							
Batch:	91021488 - Inspection Batch			Route:	Area 3 WK17 - Revised 22/23			Date: 05/08/2022
	No actionable defects found							
Batch:	91020665 - Inspection Batch			Route:	Area 3 WK13			Date: 14/07/2022
	No actionable defects found							
Batch:	91019000 - Inspection Batch			Route:	Area 3 WK09			Date: 07/06/2022
31013950	Rocking slabs Lift and relay x2 600 slabs	07/06/2022	50 High Street, Barnet, EN5 5SB Near bus shelter G	*HW: Footway Issue Slab	Internal		Committed	41017411
Batch:	91018995 - Inspection Batch			Route:	Ad Hoc Route			Date: 07/06/2022
31013946	Rocking slab Lift and relay x1 750 slab	07/06/2022	10a High Street, Barnet, EN5 5RU	*HW: Footway Issue Slab	Internal		Committed	41017406
Batch:	91018992 - Inspection Batch			Route:	Ad Hoc Route			Date: 07/06/2022
31013942	Dislodged kerb stone Reset 1m kerbstone and lift & relay 0.5m2 blocks	07/06/2022	1 High Street, Barnet, EN5 5UE Junction with Bedford avenue	*HW: Kerb Issue Granite Reset	Internal		Committed	41017401
Batch:	91018649 - Inspection Batch			Route:	Ad Hoc Route			Date: 26/05/2022
31013704	Reset 3m granite kerb	26/05/2022	Corner of High Street an Meadway opposite 7 High Street, Barnet, EN5 5RR	*HW: Kerb Issue Granite Reset	Internal		Committed	41017069
Batch:	91018648 - Inspection Batch			Route:	Ad Hoc Route			Date: 26/05/2022
31013703	Replace 2 sections of damaged pedestrian vision rail	26/05/2022	On central pedestrian island opposite 34 High Street, Barnet, EN5 5RU	*HW: Pedestrian Barrier Issue	Internal		Committed	41017068

Effective: 01/01/2021 to 21/02/2024

Asset Number: 1003.00 to 1003.00

Display Action Officer: No

Site: HIGH STREET (20022440)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,003.00	Asset - Locn.:	A1000_/00045 - HIGH STREET - HIGH STREET (A1000) FRO	Feature Type:	HW	Network Section	Area:	North
Batch:	91017516 - Inspection Batch			Route:	Area 3 WK05			Date: 25/04/2022
31012806	Failed patch Resurface 7m2	25/04/2022	26 High Street, Barnet, EN5 5XY	*HW: Pothole Patch <10m2	Internal		Committed	41015847
Batch:	91016068 - Inspection Batch			Route:	Area 3 WK01			Date: 29/03/2022
31011732	LFL Renew mortar around utility cover 1m2	29/03/2022	10a High Street, Barnet, EN5 5RU	*HW: Footway Issue Mortar	Internal		Committed	41014546
31011722	Carry out 4x0.5m2 pothole plug repair to deteriorating carriageway. Unable to mark due to traffic	29/03/2022	9a High Street, Barnet, EN5 5UE	*HW: Pothole Up To 0.5m2	Internal		Committed	41014535
31011721	Carry out 0.5m2 pothole plug repair	29/03/2022	7d High Street, Barnet, EN5 5RR	*HW: Pothole Up To 0.5m2	Internal		Committed	41014534
Batch:	91014740 - Inspection Batch			Route:	Area 3 WK45			Date: 01/03/2022
31010580	Plug repair 4x 0.5m2 forming potholes. Unable to marked as very busy High Street	01/03/2022	9a High Street, Barnet, EN5 5RR	*HW: Pothole Up To 0.5m2	Internal		Committed	41010138
31010579	Plug repair large pothole 2x0.5m2	01/03/2022	7d High Street, Barnet, EN5 5RR	*HW: Pothole Up To 0.5m2	Internal		Committed	41012965
Batch:	91013565 - Inspection Batch			Route:	Ad Hoc Route			Date: 03/02/2022
31009565	Refresh ALL white line markings from Wood Street junction to Meadway junction. This includes keep clears, centre line, lane markings, stop lines, junction arrows, zigzags and studs.	03/02/2022	High Street Barnet EN5 from junction of Wood Street to junction of Meadway.	HW: Road Marking Issue	Internal		Committed	41011311
Batch:	91013416 - Inspection Batch			Route:	Area 3 WK41			Date: 31/01/2022
	No actionable defects found							
Batch:	91012188 - Inspection Batch			Route:	Area 3 WK37			Date: 06/01/2022
31008626	Carry out 2m2 patch repair to deteriorating carriageway, hazardous to cyclists	06/01/2022	7b High Street, Barnet, EN5 5UE	*HW: Pothole Patch <10m2	Internal		Committed	41010137
31008625	Plug repair 3x 0.5m2 forming potholes. Unable to marked as very busy High Street	06/01/2022	9a High Street, Barnet, EN5 5RR	*HW: Pothole Up To 0.5m2	Internal		No Action Required	
Batch:	91010776 - Inspection Batch			Route:	Area 3 WK33			Date: 29/11/2021
31007651	Renew missing mortar around utility cover 1m2	29/11/2021	9a High Street, Barnet, EN5 5UE	*HW: Footway Issue Mortar	Internal		Committed	41008951
Batch:	91010458 - Inspection Batch			Route:	Ad Hoc Route			Date: 23/11/2021
31007483	Take out 2x pedestrian guard rails and replace with new. Raised as Cat2 as on busy pedestrian crossing.	23/11/2021	34a High Street, Barnet, EN5 5RU	*HW: Pedestrian Barrier Issue	Internal		Committed	41008720
Batch:	91008762 - Inspection Batch			Route:	Area 3 WK29			Date: 02/11/2021
31006860	LFL Renew 1x750mm paving slab 1m2 Broken and rocking very loose.	02/11/2021	22 High Street, Barnet, EN5 5RU	*HW: Footway Issue Slab	Internal		Committed	41007815
31006859	Reset 1LM of dislodged sunken Granite kerb. LFL Renew 1x600mm and 1x750mm paving slabs = 1m2	02/11/2021	7b High Street, Barnet, EN5 5RR	*HW: Kerb Issue Granite Reset	Internal		Committed	41007816

Effective: 01/01/2021 to 21/02/2024

Asset Number: 1003.00 to 1003.00

Display Action Officer: No

Site: HIGH STREET (20022440)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,003.00	Asset - Locn.:	A1000_/00045 - HIGH STREET - HIGH STREET (A1000) FRO	Feature Type:	HW	Network Section	Area:	North
Batch:	91007736 - Inspection Batch			Route:	Area 3 WK25			Date: 30/09/2021
31006106	Plug repair pothole 0.5m2 vibration issue	30/09/2021	9a High Street, Barnet, EN5 5RR	*HW: Pothole Up To 0.5m2	Internal		Committed	41006911
31006105	P5 replace 1x750mm paving slab with bitmac 1m2 due to tree roots	30/09/2021	Opposite 7f High Street, Barnet, EN5 5RR	*HW: Footway Issue Slab	Internal		Committed	41006912
Batch:	91006526 - Inspection Batch			Route:	Area 3 WK21			Date: 31/08/2021
	No actionable defects found							
Batch:	91005352 - Inspection Batch			Route:	Area 3 WK17			Date: 02/08/2021
	No actionable defects found							
Batch:	91004643 - Inspection Batch			Route:	Ad Hoc Route			Date: 16/07/2021
31003860	Reset 1LM of dislodged Granite kerb. Cat1 as this is a busy section of road and could easily be tipped into the carriageway.	16/07/2021	Court House 11a High Street, Barnet, EN5 5RR Junction with Normandy Avenue	*HW: Kerb Issue Granite Reset	Internal		Committed	41004081
Batch:	91004065 - Inspection Batch			Route:	Area 3 WK13			Date: 30/06/2021
31003409	Plug repair pothole 0.5m2 as depth and placement are High risk to cyclists. This is a busy High Street.	30/06/2021	7d High Street, Barnet, EN5 5UE	*HW: Pothole Up To 0.5m2	Internal		Committed	41003547
Batch:	91003052 - Inspection Batch			Route:	Ad Hoc Route			Date: 07/06/2021
31002693	1x pot hole D.I.o. standby job	07/06/2021	7 high street barnet	*HW: Pothole Up To 0.5m2	Internal		Committed	41002761
Batch:	91002892 - Inspection Batch			Route:	Area 3 WK09			Date: 02/06/2021
31002541	Lift and relay rocking paving slab 1m2	02/06/2021	40 High Street, High Barnet, EN5 5RU By bus stop H	*HW: Footway Issue Slab	Internal		Committed	41002587
31002536	Repair deep pothole 0.5m2 very busy junction.	02/06/2021	7 High Street, Barnet, EN5 5UE	*HW: Pothole Up To 0.5m2	Internal		Committed	41002582
Batch:	91002890 - Inspection Batch			Route:	Ad Hoc Route			Date: 02/06/2021
31002526	Kerbstone Dislodged reset 3 x granite kerb and renew 3 sqm of paving 3 x 600 needed Bus suspension needed and part lane closure	02/06/2021	In Bus Stop N in High Street. Opp 7c	*HW: Kerb Issue Granite Reset	Internal		Committed	41002572
Batch:	91002572 - Inspection Batch			Route:	Ad Hoc Route			Date: 20/05/2021
31002206	Road Pothole 4sqm patch needed Best done at night with Lane closure	20/05/2021	Court House 11a High Street, Barnet, EN5 5UJ	*HW: Pothole Up To 0.5m2	Internal		Committed	41002232
Batch:	91002570 - Inspection Batch			Route:	Ad Hoc Route			Date: 20/05/2021
31002204	Faded give way intermittent lines and faded KEEP CLEAR lettering at jct of Fitzjohn Avenue an Barnet High Road.	20/05/2021	Give way and Keep clear lettering at JUNCTION OF FITZJOHN AVENUE AND BARNET HIGH STREET	HW: Road Marking Issue	Internal		Uncommitted	41002231

Effective: 01/01/2021 to 21/02/2024

Asset Number: 1003.00 to 1003.00

Display Action Officer: No

Site: HIGH STREET (20022440)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,003.00	Asset - Locn.: A1000_/00045 - HIGH STREET - HIGH STREET (A1000) FRO			Feature Type: HW	Network	Section	Area: North	
Batch: 91001477 - Inspection Batch				Route: Area 3 WK05				Date: 27/04/2021
31001148	Patch repair carriageway 5m2 due to previous failed repair. Full TM would be required.	27/04/2021	16 High Street, Barnet, EN5 5RU (Serenity Hair)	*HW: Pothole Patch <10m2	Internal		Committed	41001150
31001147	Tree surround failing causing trip hazard	27/04/2021	Outside Graseby House.	TREE ISSUE REFER	External	5390012	No Action Required	
Batch: 91000051 - Inspection Batch				Route: Area 3 WK01				Date: 30/03/2021
31000029	Kerbs dislodged & blocks missing/Reset	30/03/2021	Junction with Bedford Ave	*HW: Kerb Issue Granite Reset	Internal		Committed	41000026
31000028	Reset kerbs dislodged by buses.	30/03/2021	Within Bus Stop m	*HW: Kerb Issue Granite Reset	Internal		Committed	41000028
31000027	Carriageway deterioration/ Potholes, forming, Risk to cycles. carry out 2m2 patch repair.	30/03/2021	Outside Jetline Holidays	*HW: Pothole Patch <10m2	Internal		Committed	41000027